
Detail 6. Random Crack Detail: For Cracks Over 1/16" Width Before Surface Preparation At minimum, any large cracks over 1/16" require appropriate detailing. In some building and slab designs, excessive temperature cycling or load transfer may necessitate the detailing of all cracks.



Treatment of cracks is in anticipation of horizontal movement.

Vertical movement will telegraph through epoxy terrazzo.

Moving cracks may telegraph through terrazzo.